



TABELA DE CONVERSÃO DE POLEGADAS E MILÍMETROS

Fração de Polegadas	MM	Fração de Polegadas	MM
1/64	0,397	33/64	13,10
1/32	0,794	17/32	13,49
3/64	1,191	35/64	13,89
1/16	1,588	9/16	14,29
5/64	1,984	37/64	14,69
3/32	2,381	19/32	15,08
7/64	2,778	39/64	15,48
1/8	3,175	5/8	15,88
9/64	3,572	41/64	16,27
5/32	3,969	21/32	16,66
11/64	4,366	43/64	17,07
3/16	4,762	11/16	17,46
13/64	5,159	45/64	17,86
7/32	5,556	23/32	18,26
15/64	5,953	47/64	18,65
1/4	6,350	3/4	19,05
17/64	6,747	49/64	19,45
9/32	7,144	25/32	19,84
19/64	7,541	51/64	20,24
5/16	7,937	13/16	20,64
21/64	8,334	53/64	21,03
11/32	8,731	27/32	21,43
23/64	9,128	59/64	21,83
3/8	9,525	7/8	22,23
25/64	9,922	57/64	22,62
13/32	10,320	29/32	23,02
27/64	10,716	59/64	23,42
7/16	11,112	15/16	23,81
29/64	11,508	61/64	24,21
15/32	11,907	31/32	24,61
31/64	12,304	63/64	25,00
1/2	12,700	1	25,40